

Superfund Site Strategy Recommendation

Region 6

Site Name: TURNER BROTHERS PIPE YARD Site Number: OKD104850524

Alias Site Name(s): _____

Address: 4725 N. BOULEVARDCity/County or Parish/State/Zip: EDMOND, OKLA. 73034Recommendation:

- ☐ 1. No further action needed; no hazardous waste problem.
- ☐ 2. No further remedial action planned under Superfund; site would not score high enough using the Hazard Ranking System to be considered for the National Priorities List.
- ☒ 3. No further remedial action planned Under Superfund; action may be appropriate under other authority: RCRA ☒ NPDES _____ SPCC _____
404 _____ TSCA _____ UIC _____ SMCRA _____ State _____
Other _____.
- ☐ 4. Further pre-remedial investigative action needed under Superfund:

PA _____
SSI _____ Priority: High _____ Medium _____
LSI _____
Other _____
To be performed by _____

Discussion:

This site is under RCRA jurisdiction. As of 8/30/88 they were in compliance with Administrative Order issued by RCRA, per Sam Yates (GH-HE). No further action under CERCLA is recommended at this time.

9798534



SUPERFUND FILE

JUN 10 1992

REORGANIZED

Copies to (please list): GH-HORecommended By: Daniel Cook (GH-FS)Date: 8/30/88Approved By: Presley R. BlalockDate: 9-7-88

cc: GH-HE